

# Homeowner Grant Program



## 1360 Maple View Place, SE

Carefully scraped and cleaned porch roofs, remove existing decorative metal porch roof supports and metal railings and all related parts from side porch. Removed south upper roof gutter across this house and the adjacent house to the west. Installed new HYDRO STOP roofing/waterproofing system. Restored upper gutter cornice, installed new ogee upper roof gutter and downspouts and splashguards to match the size, profile and location of the existing gutter on this house face and across the adjacent house to the west. Restored the

existing historic window and door trims and sills. Restored the existing historic attic vent and trims. Restored the front and side entry porch wood elements. Installed new all wood 10" diameter Tuscan column on the small side porch which matched the existing south porch columns. Installed new wood porch rail system on each side of the existing concrete stairs. Paint all wood elements.



Government of the District of Columbia

Historic Preservation Office  
Office of Planning  
2000 14th Street, NW, 4 Floor  
Washington, DC 20009  
(202) 442-7600  
[www.planning.dc.gov](http://www.planning.dc.gov)

